


SERVICE EXCHANGE **500 Series Controls**





Gold Cup Pumps





Exchange Requirements

- No missing parts
- The control housing should not be cracked or physically damaged
- The control should not be severely rusted

With a returned stroker, our fully refurbished service exchange unit which has been tested and adjusted carries a 12-month warranty and would be \$1,700 plus delivery charges.

Current Offering:

S23-15290-0 EHS 5A*-001 2XP/V A/B (Atlas Copco/Epiroc)


S23-12413-0 Elec/Hyd Stroker w/ Deadband Spring Center

S23-12416-0 Elec/Hyd Stroker(5A*), DB, Metric (AtlasCopco/Epiroc)

Additional Charges:

- 5C Control \$450
- Cracked or damaged housing \$750
- Heavily rusted \$360

Quantity Discount Available!



** For further details or questions, please contact:

David Stubbs - dstubbs@fecintl.com